Date: Oct. 25, 2023

## **Service Information**

Offboard Diagnostic Information System Service (ODIS Service) Number: AOS-23-40

To All Dealer Partners,

Subject: 2023 Q5 Hotfix

Please use hotfix A\_2.32.4\_WFS5\_etron\_20231024-084024 to correct the Deactivate Production Mode test that is failing. The tester must be on ODIS Application version 23.1.1 and Audi Brand version 2.32.4.

Elsa2Go under Service References> Software/Hardware Updates category.

Subject: Deactivate Production Mode Test Hotfix Instructions

For questions or concerns, please reach out to David Provonche, 248-754-6091.

extern.dave.provonche@audi.com

Audi GFF / ODIS Validation / Service42 Research

VWGoA, Inc.

Product Quality & Technical Service

© 2023 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposited to other sites, without the prior expressed written permission of the publisher.