

Technical product information

Topic	Buzzing noise from engine area
Market area	Australia E04 Bentley rest Asia and Australia (6E04),China 723 Volkswagen (Anhui) Automotive CO (6723),China 796 VW Import Comp. Ltd (Vico), Beijing (6796),Germany E02 Bentley rest Europe (6E02),Japan E03 Bentley Japan (6E03),Korea, (South) E08 Bentley South Korea (6E08),United Arab Emirates E06 Bentley Middle East and Africa (6E06),United Kingdom E01 Bentley UK (6E01),United States E05 Bentley USA and rest America (6E05)
Brand	Bentley
Transaction No.	2053351/9
Level	EH
Status	Released for publishing
Release date	26-Sep-2023

New customer code

Object of complaint	Complaint type	Position
engine -> engine operation	noise, vibration	

Vehicle data

W12 - Bentayga - New Continental GT - GTC & New Flying Spur

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
3S31BB	2018	E		*	*	*
3S31BB	2019	E		*	*	*
3S31BB	2020	E		*	*	*
3S31BB	2021	E		*	*	*
3S31BB	2022	E		*	*	*
3S31BB	2023	E		*	*	*
3S31BB	2024	E		*	*	*
3S31EB	2021	E		*	*	*
3S31EB	2022	E		*	*	*
3S31EB	2023	E		*	*	*
3S31EB	2024	E		*	*	*
3S41BB	2019	E		*	*	*
3S41BB	2020	E		*	*	*
3S41BB	2021	E		*	*	*
3S41BB	2022	E		*	*	*
3S41BB	2023	E		*	*	*
3S41BB	2024	E		*	*	*
3S41EB	2021	E		*	*	*
3S41EB	2022	E		*	*	*
3S41EB	2023	E		*	*	*
3S41EB	2024	E		*	*	*
4V14A9	2017	E		*	*	*
4V14A9	2018	E		*	*	*
4V14A9	2019	E		*	*	*
4V14A9	2020	E		*	*	*
4V14A9	2021	E		*	*	*
4V14A9	2022	E		*	*	*
4V14A9	2023	E		*	*	*
4V14A9	2024	E		*	*	*
4V14G9	2020	E		*	*	*
4V14G9	2021	E		*	*	*
4V14G9	2022	E		*	*	*

4V14G9	2023	E		*	*	*
4V14G9	2024	E		*	*	*
ZG21BB	2020	E		*	*	*
ZG21BB	2021	E		*	*	*
ZG21BB	2022	E		*	*	*
ZG21BB	2023	E		*	*	*
ZG21BB	2024	E		*	*	*
ZG26BB	2023	E		*	*	*
ZG26BB	2024	E		*	*	*

Documents

Document name
master.xml

Customer statement / workshop findings

Workshop findings:

Buzzing noise heard at idle from the sump area when the vehicle is elevated on a workshop ramp.

The noise cannot be heard from inside the cabin or outside of the vehicle in normal circumstances.

Technical background

A buzzing noise can be generated by the oil pump when the engine is running at idle.

Production change

*

Measure

Test a comparable vehicle with the same Engine derivative.

If the same noise is apparent on the comparable vehicle and no oil pressure warnings or relevant DTC's are stored then the noise can be considered a characteristic of the vehicle and no further action should be taken.

Warranty accounting instructions

A groundless parts replacement will be debited.