

"Residual heat" button is no longer displayed in the air conditioning system operating menu following an update of the NTG7 head unit to FUP3

---

Topic number	LI83.30-P-076965
Version	1
Function group	83.30 - Air conditioning
Date	10/9/23
Validity	Model series 223 with NTG7 premium (code 534)
Reason for change	

---

## Complaint

Following a software update of the head unit to FUP3 variant 316.5 or higher, the "Residual heat" button is no longer displayed in the air conditioning system operating menu. (See picture)

Attachments	
File	Description
<a href="#">Restwärmeknopf.pdf</a>	missing menu

## Cause

A26/17 head unit MBUX software

## Remedy

There is currently no remedy available.

Replacing the hardware will not remedy the problem.

A software update is intended with the FUP4 software E444.x (planned release for Q4/23)

Symptoms
Body > Air conditioning > Air conditioning > Malfunction, residual engine heat utilization system

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note