

Technical Service Bulletin

57 Ghost Fault "B200096: Control Module Faulty, Symptom 131164" Stored in 0046 57 23 24 2072187/1 November 22, 2023.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A6 allroad, S6, RS 6, A7, S7, RS 7, A8, S8, Q5, Q5 e quattro, Q5 Sportback, SQ5, and SQ5 Sportback	2024	All	Not Applicable

Condition

Customer states:

No customer concerns, it is found during PDI or any other diagnostic work.

Workshop findings:

The following DTC and symptom code are stored in the Comfort System Control Module, -J393- (address word 0046) even though there is no problem in the vehicle:

• B200096: Control Module Faulty (Symptom 131164)

Technical Background

Software issue in the convenience control unit -J393- (diagnostic address 0046).

Production Solution

This bulletin will be updated when more information is available. A solution is currently under development.

Service

Do not perform any repairs as there is no functional restriction. Any repairs for this concern may be denied.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information



Technical Service Bulletin

All part and service references provided in this TSB (2072187) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.