



Tips and Tricks Revision 16

Date: November 14, 2023
To: Dealer Principal, General Manager, Service Manager, North American Dealer Network
From: Richard Kenton, Technical Director
Dan Schwartz, Service Area Manager

Dear Dealers,

This bulletin is to notify you of important updates included with the recent release of Tips and Tricks Revision 16. A brief summary of each new addition is listed below, but please review the complete document hosted on DCS for further details. [Ducati - Bulletins](#)

Revision 16 New Additions		
#	Subject	Model Affected
1	Information on the different orientation of side stand springs	MULTISTRADA
2	Configuration of aluminum side panniers (in fixed or swinging mode)	MULTISTRADA
3	No DESMO Service warning light reset on instrument panel - Wrong mileage deadline	PANIGALE
4	Final drive chain oxidation	ALL MODELS

This bulletin is only applicable for Ducati Motorcycles manufactured and configured for the Ducati North American market (USA, Canada and MX).

For questions about this Service Bulletin,
please contact your Service Area Manager.