

WPN4 Workshop campaign - Re-programming Park Assist control unit

WPN4 Workshop campaign - Re-programming Park Assist control unit

ID Number	WPN4
Models	Macan (95B)
Model Years	2022-2024
VIN List	Attached
Number of Affected VINs	43,646
Issue Description	<p>On the affected vehicles, the automatic activation of the parking aid when approaching narrow obstacles in the front right outside detection area is not detected under certain conditions and is therefore not activated.</p> <p>For this reason, the Park Assist control unit on the affected vehicles must be re-programmed with a corrected data set.</p>
What should Porsche Centers do?	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles.</p> <p>As of the time of this posting (11/9/23) the remedy is now available.</p>
TI Number	No. 154-23

Required software

PIWIS Tester 4 test software version	42.250.030 (or higher)
--------------------------------------	------------------------

Warranty processing

Validity:

This workshop campaign will be carried out up to November 1st, 2028 and will be closed on that date.

Please note that warranty claims can only be processed up to this date.

WPN4 Workshop campaign - Re-programming Park Assist control unit

Scope 1: Re-programming Park Assist control unit

Damage Number	WPN4 66 000
Repair Code	1
Labor time	30 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

Attachments

1. [VIN_List_Report_WPN4_2023-11-09.xlsx](#)