

POWERTRAIN

COOLANT LEVEL CHECK ON PDI FOR MHEV/PHEV SYSTEM- 3.0 AND 4.4L

Range Rover

- 24MY Range Rover
- 24MY Range Rover Sport

Customer Voice:

- EV not available warning on Instrument cluster.

Technical Description:

- The coolant level from factory fill might be insufficient on PDI

Status:

- Please check the coolant level for the MHEV/PHEV system
- Remove the left under shield.
- Top off coolant as needed to fill to MAX line.

Refer to TOPIx section:613-01: Electric vehicle, Cooling System

