

GPOP - Issue Review System

Part Number: 68282215A\$

Part Description: Switch-Mirror

Issue Before replacing this Switch, please follow the service procedures to properly diagnose it: 1)
Description: Remove the switch 2) Please check the continuity on each pin of the switch based on the table found in the service Procedures. If after testing switch is still faulty, please call FCA Redacted Content. If no response after 15 minutes, proceeds with switch replacement.