

Delivery Stop K 1600 GT/GTL and K 1600 Bagger /Grand America

STOP130011 – Checking Fuel Hose Connection

BMW is announcing a delivery stop STOP130011 for K 1600 GT/GTL (K48) and K 1600 Bagger /Grand America (K61) produced between 09/24/2021 and 01/11/2024.

On affected vehicles, a clamp on the fuel hose (quick coupling connector to the fuel pump) can happen to be crimped insufficiently. During the motorcycle starting process, the fuel system develops a higher pressure than while riding. This increased pressure during start-up can cause the fuel hose to move on the quick coupling connector and over time could eventually slip off the quick connector coupling. As a consequence, small amounts of fuel can spill under the parked vehicle and the engine will not start.

Affected vehicles are flagged in AIR (Aftersales Information Research) with campaign code STOP130011. Please note, open campaigns or vehicle stops may not appear in DCS Warranty Vehicle Inquiry or sales systems until 24-72 hours after they are announced, therefore AIR is always the recommended method for determining open campaigns and vehicle stops.

If you have a vehicle in your new/used inventory matching the above description it cannot be retailed until repaired.

Next steps are being determined. Early indication is that no parts will be required (pending confirmation with official Service Information Bulletin). The bulletin with technical measures will be published once all information is available.

Jan 26, 2024