



Release Notes for APX™ SW7 Software

Released Version

09.70.00

1/9/2024

Models Affected

List of Features	
1	Required for use with 12-00663-16 display
2	Leap year (2024) date calculation correction (A00060)
3	2-way command override of intellisets setpoint lock
4	Display lock screen configuration
5	Allow pretrip if unit is in ferry mode and operating in diesel mode
6	Remove A73 alarm from pretrip when no AC power is set to ferry and standby mode is active
7	Support Vector 8400 model

Vector™	
HE 19	8400
X	X
X	X
X	X
X	X
X	X
X	X
X	X