

POWERTRAIN

TRANSMISSION LEAK DIAGNOSIS- NC11

Customer Voice:

- JLR Retailers have reported some NC11 equipped vehicles have a slight transmission fluid leak/seepage from the output shaft.

Technical Description:

- The concern is currently under investigation.

Status:

- Please follow the TOPIx diagnosis for fluid leak detection.
- If you do find any seals leaking, confirm with leak detection spray and open a TA for further support..

Refer to TOPIx: 311-01C: Automatic Transmission - V8 T/C 4.4L Petrol

Range Rover

- 24MY Range Rover
- 24MY Range Rover Sport

