

WPQ2 Workshop Campaign - Re-coding loudspeaker amplifier (Bose)

WPQ2 Workshop Campaign - Re-coding loudspeaker amplifier (Bose)

ID Number	WPQ2
Models	911 (992)
Model Years	2022 - 2023
VIN list	Attached
Number of Affected VINs	23
Issue Description	<p>After carrying out the workshop campaign WPJ6, there may be sound quality complaints on the affected vehicles due to incorrect coding.</p> <p>In order to correct this, the control unit of the loudspeaker amplifier (Bose) must be re-coded with an updated data set on the affected vehicles.</p> <p>Minimum requirement: Release 42.250.050.</p>
What should Porsche Centers do?	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles.</p> <p>As of the time of this posting (1/19/24) the remedy is now available.</p>

TI Number [No. 165-23](#)

Required software

PIWIS Tester 4 test software release 42.250.050 (or higher)

Warranty processing

Validity:

This workshop campaign will be carried out up to November 1st, 2028 and will be closed on that date. Please note that warranty claims can only be processed up to this date.

Scope 1:

Damage Code WPQ2 66 000

WPQ2 Workshop Campaign - Re-coding loudspeaker amplifier (Bose)

Repair Code	1
Labor time	25 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

Attachments

1. [VIN_List_Report_WPQ2_2024-01-19_V2.xlsx](#)