

WPR8 Workshop Campaign – Checking crankcase sensor and reworking if necessary

WPR8 Workshop Campaign - Checking crankcase sensor and reworking if necessary

ID Number	WPR8
Models	Cayenne (9YA / 9YB)
Model Years	2024
VIN List	Attached
Number of Affected VINs	194
Issue Description	<p>On the affected vehicles, there is a possibility that the crankcase sensors were not engaged correctly during production.</p> <p>Therefore, it cannot be ruled out that damage within the sensor may occur over the vehicle's life, due to the vibration load during vehicle operation. Subsequently, this can result in activation of the Check Engine light (MIL).</p> <p>In order to prevent this, the crankcase sensors on the affected vehicles must be checked and locked correctly if necessary.</p>
What should Porsche Centers do?	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles.</p> <p>As of the time of this posting (1/19/24) the remedy is now available.</p>
TI Number	No. 189-23

Warranty processing

Validity:

This workshop campaign will be carried out up to January 3rd, 2029 and will be closed on that date.

Please note that warranty claims can only be processed up to this date.

Scope 1: Checking crankcase sensor

WPR8 Workshop Campaign – Checking crankcase sensor and reworking if necessary

Damage Code	WPR8 66 000
Repair Code	1
Labor time	38 TU
Scope 2: Checking and reworking crankcase sensor	
Damage Code	WPR8 66 000
Repair Code	1
Labor time	61 TU
Scope 3: Replacing crankcase sensor and oil separator on one side	
Damage Code	WPR8 66 000
Repair Code	2
Labor time	80 TU
Scope 4: Replacing crankcase sensor and oil separator on both sides	
Damage Code	WPR8 66 000
Repair Code	2
Labor time	103 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle

Customer mobility

Valid only for Scopes 2 to 4:

If requested, mobility for the affected customer can be guaranteed by offering a suitable replacement vehicle. Please invoice this additional service via WWS with the campaign scope.

Attachments

1. [VIN_List_Report_WPR8_2024-01-19_V2.xlsx](#)