



Bulletin No.: PIT6104A
Published date: 01/12/2024

Preliminary Information

PIT6104A Power Liftgate Opens and then Reverses

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Blazer EV	2024	All	All	All	All

Involved Region or Country	North America
Condition	Some customers may comment that when they open the liftgate it opens all the way and then reverses to close as if it came in contact with an object.
Cause	The liftgate module may have not been properly calibrated for the actuator length.

Correction:

Perform liftgate calibration with scan tool.
 Follow: K194 Rear Gate Module> Configuration/Reset Functions> Remove/Reset Module>Liftgate Maximum Open Position Learn.
 Set the liftgate height to custom in the settings menu.
 On the radio screen go to Vehicle>Comfort and Convenience>Power Rear Gate Opening> Select Custom.
 This will limit how far the liftgate will open.
 Advise the customer that a future software update will permanently resolve this concern and at that time the liftgate could be set to open fully.
 IVH will be updated for the vehicle when the software becomes available so that the customer can be notified.

Warranty Information

Version History

Version	2
Modified	12/19/2023 - Created on. 01/12/2024- Updated correction information.

