

Technical Service Bulletin



46 TT RS Brake noise

46 12 25 2028811/2 September 26, 2012. Supersedes Technical Service Bulletin Group 46 number 12 – 21 dated February 29, 2012 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
TT RS	2012 – 2013	All	Not Applicable

Condition

The customer may complain of a high pitch squeal or squeak from the brake system when braking at slow speeds. This only applies to vehicles with brake pads and discs that still have a significant life left.

Technical Background

Natural frequency of brake components - other than the brake pads and discs.

Production Solution

A service solution is being developed.

Service

1. Verify the customer complaint matches the Condition described at the top of this TSB. Complaints not related to the Condition described in this TSB may require further diagnosis.
2. Explain to the customer that a solution is forthcoming and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve customers concern.



Tip: With careful consideration of the traffic situation, perform 2-3 ABS stops (e.g. from speeds above 50 MPH). Between each stop, please allow the brake components to cool. (Drive vehicle for more than 1 minute at speeds greater than 50 MPH.)

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Technical Service Bulletin



Additional Information

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.