

## Rear Spoiler Sporadically Inoperable with Fault Message in Instrument Cluster

---

Topic number	LI77.25-P-076544
Version	3
Function group	77.25 - Wind deflector (spoiler)
Date	2/14/24
Validity	Model series 232 - details of country variants, see remedy
Reason for change	Remedy revised

---

### Complaint

Rear spoiler sporadically remains in opened or closed position and a fault message appears in the instrument cluster. The rear spoiler can then no longer be actuated manually using the button.

The function of the rear spoiler is re-established after an ignition reset and the fault message is no longer present in the instrument cluster.

### Cause

Software of the AMG DRIVE UNIT.

### Remedy

Valid for all vehicles of model series 232 with M177 (SL55/63) from start of production - end of modification year 22/1 - manufacturing date before April 21, 2023:

--> Perform software update of the AMG DRIVE UNIT N145/1 to A 001 902 49 02.

All vehicles of model series 232 with M177 (SL55/63) from start of modification year 22/2 - manufacturing date on/after April 21, 2023:

--> Perform software update of the AMG DRIVE UNIT N145/1 to A 000 902 61 96.

Valid for all vehicles of model series 232 with M139L (SL43) from start of modification year 22/1 - manufacturing date on/after April 21, 2023:

--> Perform software update of the AMG DRIVE UNIT N145/1 to A 000 902 61 96.

**NOTE:** The information contained in this document is intended for use by trained, professional technicians with the knowledge to properly and safely perform diagnosis and repairs on Mercedes-Benz vehicles, using Mercedes-Benz approved tools and equipment. It informs service technicians about conditions that could occur in certain vehicles and provides information that could assist in proper vehicle diagnosis, service, or repair. It does not indicate that a defect is present in any vehicle referenced in this document nor does it imply warranty coverage. DO NOT assume that a symptom or condition, or a described cause of a symptom or condition, affects any particular vehicle or groups of vehicles, or that a described repair applies to any particular vehicle or groups of vehicles. There can be multiple causes resulting in the same or similar symptoms or conditions described in this document, and trained professional service technicians must use their diagnostic skills to make evaluations on a case-by-case basis. The information contained in this document does not guarantee warranty coverage nor does it extend the vehicle's warranty in any way.

## Symptoms

Body > Body/Cab > Spoiler > Does not move in/out

## Control unit/fault code

Control unit	Fault text
N4 - On-Board Diagnostics (DRVU) (DRVU3)	

## Operation numbers/damage codes

Op. no.	Operation text	Time	Damage code	Note
---------	----------------	------	-------------	------