


# ASCM Replacement

DATE: February 8, 2024

This document aims to provide additional technical information in the event of replacing the ASCM control unit for Levante.

**MODEL:** Levante M161 (All MY)

**SECTION:** 06.90 - 1 ELECTRONIC CONTROL (SUSPENSION)



The screenshot displays a technical manual interface for the ASCM replacement procedure. It includes a car diagram with callouts for various components, a parts list table, and navigation icons.

Pos	Codice	Qta	Descrizione		
7	670105688	1	NODO CONTROLLO SOSPENSIONI Non più disponibile presso la sede, verificare lo stock in loco	⚠	🔧
7	670105849	1	NODO CONTROLLO SOSPENSIONI Non più disponibile presso la sede, verificare lo stock in loco	⚠	🔧
7	670295117	1	NODO CONTROLLO SOSPENSIONI		🔧

**ACTION:** If it becomes necessary to replace the ASCM module on M161 for any reason, proceed as follows:

- **For M161 from MY 17 to 20:** (included) Open a BOL as "SUPPORT REQUEST" and note that you are requesting to replace the ASCM (Example: "Opening a BOL to request correct ASCM SW for MY17 to 20"). **Do not perform any ASCM updates unless requested by the BOL specialist.**
- **For M161 from MY 21 onwards:** Proceed as per the procedure in the workshop manual (Procedure 06.90.001 - 00 "SHOCK ABSORBER ECU - Removal/refitting or replacement")