



*Maserati*

PERSONAL SERVICE LAB

MASTERS OF CARE

# Maserati Emblem Polishing Guidelines


DATE: February 1, 2024


Caution when using an orbital machine when polishing:

Due to anomalies found on the MASERATI oval emblems of some cars on the field, a chemical analysis of the components was performed. This applies to all Maserati vehicles equipped with the oval emblem (sedans, SUVs, cabrio, and coupé).



The result of the analysis confirmed not only a lack of the coating material but also a lack of paint caused by a polishing of the component done using an orbital polishing machine.





**For this reason, it is recommended to educate the customer to avoid the polishing of the oval emblems using an orbital polishing machine.**

For the reasons mentioned earlier, any potential damage to the emblem cannot be claimed under warranty.

Please do not hesitate to contact us with any questions you may have.

Kind regards,

[Redacted signature block]

TECHNICAL SERVICE OPERATIONS