WRA5 Workshop campaign - Replace wiper blades

WRA5 Workshop Campaign - Replace wiper blades

ID Number	WRA5	
Models	Cayenne (9YA / 9YB)	
Model Years	2024	
VIN List	Attached	
Number of affected VINs	518	
Issue Description	Due to a manufacturing error, the wiper blades instal- led ex-works on the affected vehicles do not meet the required specifications.	
	Under certain circumstances, this can lead to reduced wiping performance.	
	For this reason, the wiper blades must be replaced on the affected vehicles.	
What should Porsche Centers do?	Please arrange for this measure to be carried out as soon as possible on affected vehicles. As of the time of this posting (3/1/24) the remedy is now available. Parts can be ordered via PPL as normal.	
Technical Information See below	Replace wiper blades according to RL922719 "Remo- ving and installing wiper blade". Required part num- bers: 9Y1955329A - 1 set of left-hand drive wiper bla- des (scope 1). Please note: No additional technical in- formation is provided.	

Required parts

Part number	Designation	Quantity/vehicle	Parts return*
Scope 1: 9Y1955329A	Wiper blades (left-hand drive, M-no. L0L)	1 set	No

*The parts must be stored until such time as the related warranty or campaign claim has been credited. If a barcode is generated with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the remanufactured parts process or be scrapped.

Warranty processing

Validity:

This workshop campaign will be carried out up to February 7th, 2029 and will be closed on that date. Please note that warranty claims can only be processed up to this date.

Scope 1 and 2:	
Damage Code	WRA5 66 000
Repair Code	2
Labor time	15 TU

Please enter the campaign carried out in the Warranty and Maintenance logbook for the vehicle.

Further Information

Technical Information

See example image below.

No separate technical information is available for this campaign.

Information on how to perform this campaign is displayed in the PCSS "Vehicle" menu in the "Campaign information" window.

The campaign information can be accessed via the "Additional information" button for the respective campaign.

III 🖌 🏫 😝 Vehicle 👌 Job management	i Information media	Q Communication Cockpit	
Identification via VIN Identification via vehicle data Q WP1AA2AYORDA01378 X → C@P	Charging products	Campaign information	×
	Vehicle identification number Order type	Campaign Campaign start code for PIWIS Tester Required PIWIS Tester Version	WRA5 Replacing wiper blades - -
Model year There ar		P Comment	Replace wiper blades according to RL922719 'Removing and installing wiper blade'. Required part numbers: 9/1955329A 1 set of left-hand drive wiper blades (scope 1) or 9/2955329A 1 set of right-hand drive wiper blades (scope 2). Please note: No additional technical information is provided.
Campaigns 1		Sales stop new cars	No
		Delivery stop for new cars	No
WRA5 Replacing wiper blades		Sales stop pre-owned cars	No
Closed campaigns 2		Delivery stop for pre-owned cars	No
Warranty data Vehicle description and general information			× Close

Example of technical information from PCSS.

Attachments

1. VIN_List_Report_WRA5_2024-03-01_V2.xlsx