

SSM76110 - L460 / L461 NC11 SHOWROOM FUSE REMOVAL - MY24 ONLY

Retailer voice: Battery fault on IPC when vehicle stored in showroom.

Technical Description:

- NC11 vehicle on display e.g. in a showroom while being supported by a showroom 12v support unit, it requires an additional fuse to be removed to prevent the MHEV (48v) battery draining and causing the cells to drop to a non-recoverable level.
- Vehicle activity resulting in the 48v battery cells depleting to a point where they cannot be recovered.

Status:

- Fuse F16 (5A) within the Passenger Junction Box D (KL30 Supply) must be removed along with others described in **TOPIx 101-02: Showroom preparation**.

Range Rover

- 24MY Range Rover
- 24MY Range Rover Sport

Before the vehicle is displayed in a showroom, the following fuses must be removed to prevent accidental function.

FUNCTION	FUSE	RATING	LOCATION
Horn	F1	15amp	Engine Junction Box (EJB)-C
Front and Rear washer	F2	25amp	EJB-C
Headlamp washers	F11	25amp	EJB-C
Starter motor	F26	30amp	EJB-C
Belt Integrated Starter Generator (BISG)	F5	5amp	EJB-A
Front wiper	F2	30amp	EJB-A
Rear wiper	F7	15amp	Rear Junction Box (RJB)-G

PASSENGER JUNCTION BOX - D

Publication Part No. EJLR 06 24 21_1E

