

Vibrating Noises From the Area of the 2nd Row Seat Backrest When Driving

Topic number	LI91.12-P-077720
Version	1
Function group	91.12 - Rear seats
Date	4/15/24
Validity	Model series 296 with code 803
Reason for change	

Complaint

Vibrating noises from the area of the 2nd row seat backrest when driving

Attachments	
File	Description
IMG_4065.MOV	Customer complaint

Cause

Tolerance between 2nd seat row seat backrest and load compartment trim

Remedy

Perform software update in the rear passenger compartment seat control units

Symptoms
Body > Body/Cab > Body noises > Vibrates/makes noises
Body > Seat > Noises > Cracking
Body > Seat > Noises > Grunting
Body > Seat > Noises > Knocks

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note