SB-10025669-6336



Service Bulletin

File In Section: 09 - Restraints

Bulletin No.: 08-09-41-006A

Date: February, 2009

TECHNICAL

Subject: SIR/Airbag Light Illuminated, DTC B0081 (Passenger Presence System (PPS)

Code) Stored (Inspect PPS System Connectors)

Models: 2006-2009 Chevrolet Cobalt, HHR

2006 Pontiac Pursuit (Canada Only)

2007-2009 Pontiac G5

This bulletin is being updated to add model years. Please discard Corporate Bulletin Number 08-09-41-006 (Section 09 — Restraints).

Condition

Some customers may comment that the SIR light is illuminated.

Upon investigation, the technician may find the following Passenger Presence System code codes stored:

- DTC B0081 3A: Passenger Presence System Incorrect Component Installed
- DTC B0081 39: Passenger Presence System Internal Electronic Failure
- DTC B0081 71: Passenger Presence System Invalid Serial Data Received
- With Passenger Presence System (PPS) Flash Code of DTC 023

Note: You will only find this DTC 023 by going through the (PPS) menu

Correction

Technicians are to inspect the electrical connections to all the PPS components.

- Inspect the PPS module connector, the pressure sensor connector and the seat connector (all located under the front passenger seat).
- Inspect the connector of the belt tension sensor (BTS) that is part of the retractor assembly (located between the floor pan and the carpet under the front passenger seat).
- 3. Clear the codes.
- 4. Verify that the DTC does not reset.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
N6624	Wiring and/or Connector – Occupant Safety — Repair or Replace	Use Published Labor Operation Time