

SB-10044298-2056



Countries:	CANADA, UNITED STATES	Document ID:	IK2600176
Availability:	Internal - Attachable	Revision:	0
Major System:	PROGRAMMING SUPPORT	Created:	5/3/2012
Current Language:	English	Last Modified:	5/24/2012
Other Languages:	NONE	Author:	AI Schnellenberger
Viewed:	20		

[Less Info](#)

Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 2	Not Helpful 2
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	-------------------------	-----------------------------

Title: BE/CE Bus Pupil Warning Light Programming

Applies To: BE CE

DESCRIPTION

This article provides tables, identifying the ESC/BC programming, affecting Pupil Warning Light operation.

RESOLUTION

Refer to the applicable tables, at the link below, for acceptable Pupil Warning Light Feature configurations.

[Post 2007 Pupil Warning Light Programming](#)

[Pre 2007 Pupil Warning Light Programming](#)

Hide Details

Feedback Information

Viewed: 19
Helpful: 2
Not Helpful: 2
No Feedback Found

Copyright © 2012 Navistar, Inc.