

Fault message in display - Right rear turn signal light inoperative

Topic number	L182.10-P-053604
Version	1
Design group	82.10 Exterior lights
Date	04-18-2012
Validity	W and C 204
Reason for change	
Reason for block	

Complaint:

Fault message in display - Right rear turn signal light inoperative.

Cause:

Currently under analysis.

Remedy:

As the topic is still under analysis, please do not replace any parts (rear SAM - lamp carrier - rear lamps).

You will be notified via TIPS as soon as a remedy is known.

Symptoms
Lighting / Nonfunctional / Overall vehicle / Turn signal/hazard warning lights indicator lamp / Turn signal indicator / Exterior lights / Turn signal/hazard warning lights /
Lighting / Nonfunctional / Overall vehicle / Turn signal lights / Exterior lights / Turn signal/hazard warning lights /

Work units				
Op. no.	Operation text	Time	Damage code	Note
			82202 52	Taillamp turn signal light

Validity		
Vehicle	Engine	Transmission
204.000	*	*
204.001	*	*
204.002	*	*
204.003	*	*
204.006	*	*
204.007	*	*
204.008	*	*

XENTRY

204.022	*	*
204.023	*	*
204.025	*	*
204.031	*	*
204.034	*	*
204.041	*	*
204.044	*	*
204.045	*	*
204.046	*	*
204.047	*	*
204.048	*	*
204.049	*	*
204.052	*	*
204.054	*	*
204.055	*	*
204.056	*	*
204.057	*	*
204.065	*	*
204.077	*	*
204.080	*	*
204.081	*	*
204.082	*	*
204.085	*	*
204.087	*	*
204.088	*	*
204.089	*	*
204.092	*	*
204.302	*	*
204.303	*	*
204.331	*	*
204.347	*	*
204.349	*	*
204.357	*	*
204.377	*	*
204.388	*	*