



March 2013

Technical Service Bulletin Notification TSB#13-001

Dear Jayco Dealer:

Jayco has determined that on certain model year 2013 Jay Flight Travel Trailers the power cord requires a hook to hold it away from the furnace exhaust.

The coverage period for this Technical Service Bulletin is for one (1) year from the release of this notification. If you have any questions on this Bulletin, please contact our Customer Service department at 800-283-8267. A copy of the bulletin is attached.

We apologize for this inconvenience. However, we are confident that this improvement will offer continued satisfaction with Jayco brand products.

Sincerely,

Jayco, Inc.