

[Next Unread Message](#)**View Message****Sent on** 09 05 2013 **Expires on** 09 18 2013**From** Parts and Service Division**Subject** Request for Parts: 2013 ILX 12V Battery Failure

**To:** All Acura Service Managers/Consultants  
**From:** Technical Research & Support Group  
**RE:** Request for Parts: 2013 ILX 12V Battery Failure

Print this *iN* message and provide a copy to the Shop Foreman and all Service Consultants.

**Background**

American Honda (AHM) is investigating certain 2013 ILXs with a customer complaint of a no-start condition which requires the 12V battery to be replaced.

To fully understand the cause of this occurrence, AHM would like to collect a certain part prior to you attempting a repair of any kind.

**Action Required**

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2013, American Honda Motor Co., Inc. All Rights Reserved.