



Classification:

EC09-002f

Reference:

ITB09-012f

COPYRIGHT © NISSAN NORTH AMERICA, INC.

Date:

November 15, 2013

2007 – 2011 EVAP LEAK DTC P0442, P0455, P0456 INFORMATION

This bulletin has been amended. Changes have been made throughout.
Please discard previous versions of this bulletin.

APPLIED VEHICLES: 2007 - 2011 Infiniti vehicles

NOTE: For 2012 and newer vehicles, refer to ITB13-044.

SERVICE INFORMATION

If one or more of these EVAP leak DTCs are stored (**P0442, P0455, P0456**) on a 2007 through 2011 Infiniti vehicle, **a loose fuel fill cap may be the cause.**

Use the following resources to perform diagnostics and confirm the cause of stored DTCs.

ASIST:

- Appropriate Service Manual diagnostic procedures
- Applicable Technical Service Bulletins (TSB).

Leak Test:

- With CONSULT-III plus - WORK SUPPORT >> EVAP SYSTEM CLOSE.
NOTE: Use Essential Tool J-42909 or equivalent to pressurize the EVAP system.
- With a "Smoke" leak detection machine. Refer to the machine's Operator's Manual for proper use.

Make sure the customer is informed of the proper fuel filler cap installation.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, **DO NOT** assume that it does. See your Infiniti dealer to determine if this applies to your vehicle.