




---

# SERVICE BULLETIN

---

Classification:

EC09-001f

Reference:

NTB09-020f

Date:

November 15, 2013

## 2007-2011 EVAP LEAK DTC P0442, P0455, P0456 INFORMATION

This bulletin has been amended. Changes have been made throughout.  
Please discard previous versions of this bulletin.

**APPLIED VEHICLES:** 2007 - 2011 Nissan vehicles

**NOTE:** For 2012 and newer vehicles, refer to NTB13-097.

### SERVICE INFORMATION

If one or more of these EVAP leak DTCs are stored (**P0442, P0455, P0456**) on a 2007 through 2011 Nissan vehicle, **a loose fuel fill cap may be the cause.**

Use the following resources to perform diagnostics and confirm the cause of stored DTCs.

#### ASIST:

- Appropriate Service Manual diagnostic procedures
- Applicable Technical Service Bulletins (TSB).

#### Leak Test:

- With CONSULT-III plus - WORK SUPPORT >> EVAP SYSTEM CLOSE.  
**NOTE:** Use Essential Tool J-42909 or equivalent to pressurize the EVAP system.
- With a "Smoke" leak detection machine. Refer to the machine's Operator's Manual for proper use.

**Make sure the customer is informed of the proper fuel filler cap installation.**

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, **DO NOT** assume that it does. See your Nissan dealer to determine if this applies to your vehicle.