

SB-10054091-9791**View Message**

Sent on 09 12 2013 **Expires on** 09 25 2013
From Parts and Service Division
Subject Request for Visit: 2004-2008 TSX Engine Hesitation

To: All Acura Service Managers/Consultants
From: Technical Research & Support Group
RE: Request for Visit: 2004-2008 TSX Engine Hesitation

Print this *iN* message and provide a copy to the Shop Foreman and all Service Consultants.

Background

American Honda (AHM) is investigating certain 2004-2008 TSXs with a complaint of the engine hesitation. To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. Engine hesitation must be duplicated.
2. Negative Battery Cable has not been touched during this visit.

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000-2013, American Honda Motor Co., Inc. All Rights Reserved.