Advanced Full Text Search - TIBU7225 - Proactive Inspection Sheet for Certain CT660 ... Page 1 of 3 SB-10054500-9842

CATERPILLAR ®	Service Information System	Shutdown SIS
Previous Screen		
		Welcome: chrismk2
B . L. L. NO FOURDMENT OF FOT		

Product: NO EQUIPMENT SELECTED
 Model: NO EQUIPMENT SELECTED
 Configuration: NO EQUIPMENT SELECTED

Technical Information Bulletin

 Proactive Inspection Sheet for Certain CT660 On-Highway Trucks{7000}

 Media Number -TIBU7225-00
 Publication Date -03/09/2013

 Date Updated -03/09/2013

 Caterpillar: Confidential Yellow

i05425816

Proactive Inspection Sheet for Certain CT660 On-Highway Trucks{7000}

SMCS - 7000

On Highway Truck: CT660 (S/N: TKL1-UP; TRK1-UP; TSY1-UP)

Introduction

This Technical Information Bulletin provides information needed for proactive inspections for certain Cat CT660 On-Highway Trucks.

Problem

Certain Cat CT660 On-Highway Trucks could experience known product early hour failures. Machines that are possibly affected include:

- (S/N: TLK101-472)
- (S/N: TRK107-1549)
- (S/N: TSY113,137)

Solution

These trucks will benefit from the completion of the following proactive truck inspection. One by one go through the inspection sheet and perform all known documented repairs to each and every item on the check sheet. Proper execution of these repairs will help reduce customer failures and down time.

Table 1 Inspection Process Sheet CT660				
1. Check for and apply all open "Service Letters" (Office Support).				
Check ET for Automatic Transmission Fault Codes.				
3. Connect Engine Diagnostics and Check for Fault Codes.				
Under Hood Inspection				
1. Install 423-8712 Gasket for the Intake Throttle Valve if not already installed.				
2. Inspect grill mounting				
3. Inspect elbow coming from air charge cooler making sure that spring is in place.				
4. Inspect Dipstick Tube for tube mounting brackets.				
5. Inspect Radiator support Bracket.				
Interior Cab Inspection				
1. Inspect operation of all gauges in Dash cluster				
2. Inspect HVAC ground wire				
3. Operation of power windows. (should be fast and smooth not slow or binding)				
4. Inspect seat cover material for flaws. (torn material stitches separated)				
Chassis Inspection				
1. Inspect Wheels / Axles / Transmission / Engine for leakage. Recheck torque on axle studs / nuts.				
2. Check carrier bearing alignment with Driveshaft components.				

3. Check all Chassis and Engine wiring harnesses for rubbing/ chaffing / secure	
4. Inspect air suspension and brake lines for rubbing / chaffing / secure	
5. Check operation of Lift Axle for proper operation of controls and pressure switches.	
6. Check ride height.	
7. Inspect weld joint of torque arm on front and rear."Primaax only"	
Remove Quarter Fender and DOC Pipe	
1. Inspect Quarter Fender mounting. Check for installation of large body washer	
2. Wrap TE wiring harness where harness crosses EGR tube with heat resistant tape for additional harness protection	
3. Inspect EGR tube for leaks. Rev the engine to perform check. Install newest pipes as needed	
4. Inspect A/C line from dryer to expansion valve. Look for contact with brackets.	
5. Inspect exhaust system and DPF for signs of leakage / rubbing / loose clamps.	

Copyright 1993 - 2013 Caterpillar Inc. All Rights Reserved. Private Network For SIS Licensees. Wed Oct 2 17:14:47 CDT 2013 chrismk2