

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR NOVEMBER 2013**

44310 2011-2013 EDGE/MKX - POWER STEERING PUMP SQUEAL NOISE AT STEERING STOPS

SOME 2011-2013 EDGE/MKX VEHICLES BUILT THROUGH 04/30/13 MAY EXHIBIT A HIGH-PITCHED SQUEAL NOISE FROM THE POWER STEERING PUMP WHEN STEERING WHEEL IS FULLY TURNED TO EITHER LEFT OR RIGHT STEERING STOP POSITION. REPLACE POWER STEERING PUMP WITH LATEST LEVEL SERVICE PART. REFER TO WORKSHOP MANUAL, SECTION 211-02. USE EXISTING LABOR TIME OPERATION NUMBER.