

SB-10055318-4561

ONLINE AUTOMOTIVE SERVICE INFORMATION FOR MARCH 2014

44429 2006-2010 Explorer, Mountaineer, Explorer Sport-Trac "Front Wheel Speed Sensor Wire Harness Routing" Job Aid Available in Service Tips

Proper routing of the wheel speed sensor wiring harness is key to preventing harness damage that results from contact with the tire or other suspension components. A job aid has been developed that includes pictures of the correct routing and attachment points. The wheel speed sensor harness routing job aid can be found under the Service Tips Tab on the PTS website.