

SB-1005574-7472

ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM FOR FEBRUARY 2014

44420 2013 - 2014 F150 Built Through 1/31/2014 - Sunroof Track Binding

Some 2013 - 2014 F150 built on or before 1/31/2014 may exhibit a binding Sunroof concern at times. Replace the Roof Opening Panel Frame Assembly. Parts Depot stock has been purged. You will automatically receive the revised track assembly. Refer Workshop manual section 501-17 and use available Service Labor times.