

ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR FEBRUARY 2014

SB-10055589-5294

44402 6.7L - Diagnostic Trouble Code (DTC) P208E - Diesel Exhaust Fluid (DEF) Injector Testing

Some 2011-2014 F-Super Duty vehicles equipped with 6.7L Diesel engine may exhibit Malfunction Indicator Lamp (MIL) with DTC P208E stored in Powertrain Control Module memory with or without DTC P204F. Results of Selective Catalyst Reductant (SCR) dosing RK7 measurement test may be zero or below specified 45-55mL requirement due to urea crystals forming on the DEF injector nozzle. If the measurement is below the specified amount, perform diagnostic procedure RK7 two additional times and reinstall the reductant injector if dosing measurement requirement is met. If the dosing measurement remains below specified 45-55 mL requirement, the DEF injector should be replaced. The DEF pump should not be replaced for DTC P208E. Engineering investigation in progress. Monitor OASIS for future updates.