

ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR MAY 2014

SB-10056170-8164

44531 2009-2014 F-150/Taurus/Flex/MKT/MKS, 2010-2015 F-Super Duty, 2011-2014 Explorer
Power Seat Track Binding/Seized, Grind, Squeal, Popping Noise Moving Forward or
Rearward.

Some 2009-2014 F-150/Taurus/Flex/MKT/MKS, 2010-2015 F-Super Duty, 2011-2014 Explorer
vehicles may experience binding, grinding, squealing and/or popping noise when
the seat is moved forward or rearward. Service inventories have been updated
with revised seat motor/bracket kits(14547), for lower service part replacement
procedure. Follow the On-line Workshop Manual (WSM) section 501-10 for diagnostic
and replacement procedures and use available service labor operations.