

ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR MAY 2014

SB-10056200-1755

44568 2011-2015 F-Super Duty - 6.7L Diesel - Malfunction Indicator Light (MIL) On with Multiple DTC's - New Ford Fleet Upfitter QVM Bulletin # Q-221 Released.

Some 2011-2015 6.7L diesel equipped vehicles may exhibit a MIL on with various (DTC's) stored in in the (PCM). These DTC's may set, due to: loose, missing, modified or damaged ground G400, during vehicle modification(s). G400 may be relocated by body builders/Upfitters from its original location. Inspect G400 to ensure it is: Present, properly secured, clean, and that the bolt head is not broken off prior to performing normal diagnostics. G400 should be located on a main frame rail, not on a cross-member/welded extension. For fleet or upfitted vehicles refer to Quality Bulletin Modifier (QVM) Bulletin #Q-221. Refer to [HTTPS://WWW.FLEET.FORD.COM/](https://www.fleet.ford.com/) website, click on Truck Body Builder Advisory Service link and bullitens. Repairs performed due to vehicle modifications are not covered under normal vehicle manufacturers warranty.