



Service Information System

Previous Screen

SB-10056343-1633

Welcome: davidaa

◀ Product: NO EQUIPMENT SELECTED
Model: NO EQUIPMENT SELECTED
Configuration: NO EQUIPMENT SELECTED

Technical Information Bulletin

CT660 Vocational Truck Air Leak from Suspension Dump Switch or Air Tube Connection {7000}

Media Number -TIBU7707-00

Publication Date -2014/07/29

Date Updated -2014/07/29

Caterpillar: Confidential Yellow

i05876797

CT660 Vocational Truck Air Leak from Suspension Dump Switch or Air Tube Connection{7000}

SMCS - 7000

On Highway Truck:

CT660 (S/N: TGA1-UP; TGD1-UP; TJD1-UP; TEJ1-UP; TRK1-UP; TKL1-UP; TEM1-UP; TEP1-UP; TGR1-UP; TGS1-UP; TJS1-UP; TGW1-UP; TSW1-UP; TEY1-UP; TSY1-UP; TEZ1-UP; TGZ1-UP)
CT681 (S/N: TWJ1-UP)

Introduction

Suspension dump switch and tube may develop air leaks on the CT660 Vocational Truck.

Problem

The Suspension Dump Switch fails and causes air to leak from switch. In some applications the tube connected to the switch has been improperly connected and will allow air to leak.

Solution

Check the Suspension Dump Switch air tube to insure the tube is fully connected to the switch. If the air is still leaking at the switch, replace with current part until resolution is known.

[Copyright 1993 - 2014 Caterpillar Inc.](#)

[All Rights Reserved.](#)

[Private Network For SIS Licensees.](#)

Wed Aug 6 07:52:43 CDT 2014

daidaa