

**** TECHNICAL INFORMATION NOTICE ****
SB-10056653-7612

DATE: August 5, 2014

TO: Mitsubishi Motors US and Puerto Rico Dealer Principals, Service Managers and Parts Managers

RE: Front Exhaust Pipe Seal Ring Warranty Extension

TIN NO. TIN-14-15-001

AFFECTED VEHICLES: 2008 – 2011 Lancer (non-turbo), 2009 – 2011 Lancer Sportback (non-turbo), 2008 – 2011 Outlander (2.4L Engine), and 2011 Outlander Sport

PURPOSE

A warranty extension for the front exhaust pipe seal ring will be launched today on all 2008 – 2010 Lancer (non-turbo), 2009 – 2010 Lancer Sportback (non-turbo), and 2008 – 2010 Outlander (2.4L) vehicles. Also, certain 2011 Lancer (non-turbo), 2011 Lancer Sportback (non-turbo), 2011 Outlander (2.4L), and 2011 Outlander Sport vehicles are included in this warranty extension. The original warranty term of 5 years / 60,000 miles, whichever comes first, will be extended to 10 years / 120,000 miles, whichever comes first.

The TSB outlining the warranty extension will be available today on MEDIC and MDL.

Notification letters will be sent to owners of affected vehicles, informing them of the front exhaust pipe seal ring warranty extension.

Please refer to TSB-14-15-001 or Warranty Bulletin WB 2015-004 for further information.