

44852

### 2011-2015 Fiesta/2012-2014 Focus- DPS6 Transmission ... Do Not Expose Input Shaft Seals To Solvents

On 2011-2015 Fiesta/2012-2014 Focus vehicles equipped with a DPS6 transmission when using solvents to clean the DPS6 transmission bell housing and clutch. Be careful to avoid input shaft seal exposure to solvent. If any solvent contacts the input shaft seal, wipe the area dry immediately. After cleaning the clutch assembly, allow ample time for the assembly to dry before installation. The seal could have swelled and if not completely dry when installed, may result in damage to the seal.