

 HYUNDAI NEW THINKING. NEW POSSIBILITIES. Technical Service Bulletin	GROUP CAMPAIGN	NUMBER 15-01-005
	DATE January 2015	MODEL(S) ELANTRA (HD), SONATA (YFa), ELANTRA (FD), SONATA (NFa), GENESIS (BH), GENESIS COUPE (BK)
SUBJECT: INSIDE DOOR HANDLE INSPECTION AND REPLACEMENT (SERVICE CAMPAIGN TW7)		

*** IMPORTANT**

***** Retail Vehicles Only *****

Dealers must perform this Service Campaign whenever an affected vehicle is in the shop for any maintenance or repair.

When a vehicle arrives at the Service Department, access Hyundai Motor America's "Warranty Vehicle Information" screen via WEBDCS to identify open Campaigns.

Description: On certain vehicles the interior chrome plated door handles may wear due to repeated use. The top edge of the handle may wear away as the door handle is used resulting in a separation of the plating between the inboard and outboard surfaces of the handle, and may form a rough or sharp edge. This bulletin provides the service procedure to inspect the plating on each door's inside handle and replace if necessary.



SUBJECT: INSIDE DOOR HANDLE INSPECTION AND REPLACEMENT

Applicable Vehicles:
 CERTAIN 2009-10 GENESIS SEDAN (BH)
 CERTAIN 2010 GENESIS COUPE (BK)
 CERTAIN 2009-11 ELANTRA TOURING (FD)
 CERTAIN 2010 ELANTRA SEDAN (HD)
 CERTAIN 2009-10 SONATA (NFa)
 CERTAIN 2011 SONATA (YFa)

Parts Information:

PART NAME	PART NUMBER	REMARKS	
HANDLE ASSEMBLY - DOOR INSIDE	826103M000CRQQH	FR/RR LH	GENESIS SEDAN (BH)
	826203M000CRQQH	FR/RR RH	
	826103M000CRQQH	FR LH	GENESIS COUPE (BK)
	826203M000CRQQH	FR RH	
	826102L010CRQQH	FR LH	ELANTRA TOURING (FD)
	826202L010CRQQH	FR RH	
	836102L010CRQQH	RR LH	
	836202L010CRQQH	RR RH	ELANTRA SEDAN (HD)
	826100Q000CRQQH	FR/RR LH	
	826200Q000CRQQH	FR/RR RH	SONATA (NFA)
	826103K530CRQQH	FR LH	
	826203K530CRQQH	FR RH	
	836103K530CRQQH	RR LH	
	836203K530CRQQH	RR RH	SONATA (YFA)
	826103S010CRQQH	FR/RR LH	
	826203S010CRQQH	FR/RR RH	

Warranty Information:

OP CODE	OP NAME	OP TIME	VEHICLE
40C073R0	DOOR INSIDE HANDLE INSPECTION ONLY	0.2 M/H	ALL
40C073R1	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (FR 1EA)	0.3 M/H	ELANTRA (HD)
40C073R2	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (FR 2EA)	0.4 M/H	
40C073R3	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (RR 1EA)	0.3 M/H	
40C073R4	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (RR 2EA)	0.4 M/H	

SUBJECT: INSIDE DOOR HANDLE INSPECTION AND REPLACEMENT

40C073R5	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (ALL 3EA)	0.6 M/H	
40C073R6	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (ALL 4EA)	0.8 M/H	
40C073R7	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (FR 1EA)	0.3 M/H	ELANTRA TOURING (FD) / SONATA (YF)
40C073R8	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (FR 2EA)	0.4 M/H	
40C073R9	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (RR 1EA)	0.3 M/H	
40C073RA	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (RR 2EA)	0.4 M/H	
40C073RB	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (ALL 3EA)	0.5 M/H	
40C073RC	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (ALL 4EA)	0.6 M/H	
40C073RD	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (FR 1EA)	0.3 M/H	
40C073RE	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (FR 2EA)	0.4 M/H	
40C073RF	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (RR 1EA)	0.3 M/H	
40C073RG	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (RR 2EA)	0.4 M/H	
40C073RH	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (ALL 3EA)	0.6 M/H	
40C073RJ	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (ALL 4EA)	0.7 M/H	
40C073RK	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (FR 1EA)	0.3 M/H	GENESIS (BH)
40C073RL	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (FR 2EA)	0.5 M/H	
40C073RM	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (RR 1EA)	0.3 M/H	
40C073RN	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (RR 2EA)	0.5 M/H	
40C073RP	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (ALL 3EA)	0.7 M/H	
40C073RR	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (ALL 4EA)	0.9 M/H	GENESIS COUPE (BK)
40C073RS	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (FR 1EA)	0.3 M/H	
40C073RT	DOOR INSIDE HANDLE INSPECTION AND REPLACEMENT (FR 2 EA)	0.4 M/H	

NOTE: Submit Claim on Campaign Claim Entry Screen

SUBJECT: INSIDE DOOR HANDLE INSPECTION AND REPLACEMENT

SERVICE PROCEDURE:

- 1) Open door and inspect chrome plating on all four inside door handles (A) for wear or cracking.
- 2) If door handles do not exhibit wear or cracking, procedure is complete.
- 3) If a door inside handle's plating is worn or cracked, replace it with the new one following the applicable Shop Manual.
- 4) Confirm newly installed inside door handle functions properly.

