

SB-10058183-6170

**ONLINE AUTOMOTIVESERVICE INFORMATION SYSTEM
FOR MARCH 2015**

45020 2014, 2015 Transit Connect - Air Conditioning Performance

Some 2014, 2015 Transit Connect vehicles built on or before 11/7/2014 may exhibit poor air conditioning performance and/or inaccurate airflow through the vents. Check the Recirculation Door connector C289 and Defrost Door connector C232 for potentially being swapped. Compare the wiring colors in the connector to the Wiring Diagram.