

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR MARCH 2015**

44983 2015 Transit - 3.2L Duratorq-TDCi - Check Engine Light For Reductant Pump and Reductant Line Heater - Wiring Diagram Updated - Inconsistent Wire Color

Some 2015 Transit vehicles equipped with a 3.2L Duratorq-TDCi engine and a Check Engine Light for Reductant Pressure Line Heater (CE373) or Reductant Pump Assembly Heater (CE352) may not utilize consistent wire insulation color for the entire length of the circuits. Wiring Diagram section 024-1 (pages 20 and 21) reflects this wire color change possibility. When related diagnostics are performed, make sure to follow PC/ED instruction to check circuits based on the connector pin number and location, and not insulation color. Do not unnecessarily re-pin C4470 to make insulation color match.