

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR MARCH 2015**

45002 2014 - 2015 Transit Connect - 15B02 Accessory Protocol Interface Module Programming

When performing 15B02 Accessory Protocol Interface Module (APIM) reprogram on 2014-2015 Transit Connect, ignore the PTS message 'This vehicle already has the latest level SYNC...'. This message will appear on a vehicle VIN involved in the Field Service Action because these vehicles do have the latest version of SYNC software, however, activating the SYNC 911 Assist feature can only be done through Standard APIM Programming. After reprogramming, pair a compatible phone to verify the 911 Assist feature is present.