

Normalization position of seat for active belt buckle (AGS) required

Topic number	LI91.00-P-061754
Version	1
Design group	91.00 General
Date	06-30-2015
Validity	Model series 222 (code 232 + 224 + 305)
Reason for change	
Reason for block	

Complaint:

Blocking between seat belt buckle and seat cushion.

Cause:

Incomplete normalization (the control unit detects a blockage and aborts the normalization sequence).

Remedy:

The following measure should be performed in order to avoid unnecessary additional work when normalizing the AGS in the form of retests or, in extreme cases, the removal of non-defective parts.

Before the normalization sequence is launched, the following settings must be made to the LEFT REAR SEAT and RIGHT REAR SEAT to ensure that normalization is successful.

1. Move rear seat cushion to foremost position
2. Move rear backrest to rearmost position

Symptoms
Body / Safety system / Seat belt / Seat belt buckle / Does not move in/out

Validity		
Vehicle	Engine	Transmission
S (222)	*	*

Full model designation breakdown		
Vehicle	Engine	Transmission
222.004	651.921	724.208
222.032	642.861	722.903
222.032	642.861	725.011
222.033	642.867	722.966
222.057	276.960	724.206

XENTRY

222.057	276.960	725.011
222.067	276.824	722.961
222.067	276.824	725.041
222.077	157.985	722.931
222.082	278.929	722.909
222.082	278.929	725.011
222.085	278.929	722.967
222.085	278.929	725.041
222.104	651.921	724.208
222.123	642.861	722.903
222.123	642.861	725.011
222.132	642.861	722.903
222.132	642.861	725.011
222.133	642.867	722.966
222.157	276.960	724.206
222.157	276.960	725.011
222.162	276.824	722.904
222.162	276.824	725.011
222.163	276.824	724.204
222.165	276.824	722.904
222.165	276.824	725.011
222.167	276.824	722.961
222.167	276.824	725.041
222.176	277.980	722.932
222.177	157.985	722.931
222.178	157.985	722.971
222.179	279.980	722.932
222.182	278.929	722.909
222.182	278.929	725.011
222.184	278.910	722.967
222.184	278.910	725.041
222.185	278.929	722.967
222.185	278.929	725.041
222.967	276.824	722.961
222.967	276.824	725.041
222.976	277.980	722.932
222.982	278.929	722.909
222.982	278.929	725.011
222.984	278.910	725.041
222.985	278.929	722.967
222.985	278.929	725.041