

SB-10058616-9689

## **ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM FOR AUGUST 2015**

**45277** 2013-2016 Edge, Flex, MKX, MKS, MKT, MKZ, Taurus, Police Sedan, Explorer, Police Utility - 6F50/6F55 Transmission Fluid Leak From Converter Housing

Some 2013-2016 Edge, Flex, MKX, MKS, MKT, MKZ, Taurus, Police Sedan, Explorer, or Police Utility equipped with a 6F50/6F55 transmission may exhibit a transmission fluid leak from the converter housing area. To properly diagnose, refer to the updated Workshop Manual, Section 307-01 for leakage inspection. If the leak is found to be from the converter hub seal in the transmission housing, an improved seal is available, part number 7T4Z-7F401-B. The converter hub should be inspected for visible damage or measurable wear. The torque converter can be re-used with just a 7F401 hub seal replacement.