

SB-10058629-7149

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR AUGUST 2015**

45291 Escape And Transit Connect - Front Seat Belt Blocked

Should a Customer complain about the front seat belt being blocked, this may be the activation of the back-locking effect (belt retractor safety system). Please follow these steps: If the belt height adjuster is not in the lowest position; move down to this position. If belt height adjuster is already at the lowest position, pull out continuous and strongly the webbing approximately 20 mm. and let the seatbelt retract again. Then re-check seat belt function. If it is OK, the issue is fixed. If it is not OK, you have to replace the seat belt. Refer to Workshop Manual (WSM), Section 501-20A for additional information on the Automatic Locking Retractor (ALR) mode functional test operation.