



Mercedes-Benz

The best or nothing.

**star bulletin**



Date: February 20, 2014  
 Order No.: P-B-58.40/165  
 Group: 58

**SUBJECT: MY-All, Model 222  
 Use of Regio-DVD 01/2014**

The Regio DVD 01/2014 with one of the part numbers below, may only be inserted during control unit programming via the external drive of the diagnostic system when prompted.

Regio DVD installation using the "Regio-DVD Updater" will result in faulty COMAND programming. Only insert the Regio DVD 01/2014 into the diagnostic external drive when requested to do so.

Add-on 3406, which is now available, must be installed for control unit programming.

**Regio DVDs**

HLI 000 000 16 47	Regio DVD 01/2014
HLI 000 000 16 48	Regio DVD 01/2014
HLI 000 000 16 49	Regio DVD 01/2014
HLI 000 000 16 50	Regio DVD 01/2014
HLI 000 000 16 51	Regio DVD 01/2014

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.