



**Internal notification for: G\_0000169328 12191A - Special Coverage - Fuel Odor or Spotting on Ground - Replace Fuel Pump Module - Revised**

gm\_gmssg\_q01

1

07/09/2013 05:50 AM

2 attachments



12191A bulletin.pdf



GM Style Sheet.css

Your email client does not support HTML messages

Date: 7/09/2013

Ref. number: Service / Field Action / G\_0000169328

Subject: 12191A - Special Coverage - Fuel Odor or Spotting on Ground - Replace Fuel Pump Module - Revised

GM CUSTOMER CARE AND AFTERSALES  
DCS2996  
URGENT - DISTRIBUTE IMMEDIATELY

Date: July 9, 2013

Subject: 12191A - Special Coverage Adjustment  
Fuel Odor or Spotting on Ground - Replace Fuel Pump Module

Models: 2006 Pontiac Pursuit; 2006-07 Saturn ION; 2006-09 Chevrolet Cobalt; 2007 Chevrolet Equinox and Pontiac Torrent; 2007-09 Pontiac G5 Not Involved in Safety Recall 09226 or 12190, or Special Coverage 09275  
and  
2008-09 Chevrolet Equinox and Uplander, and Pontiac Montana SV6 and Torrent

To: All GM Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, Used Vehicle Sales Manager, and Warranty Administrator

Due to part availability, Special Coverage 12191 was administered in phases. The first phase included Chevrolet Cobalt, Pontiac G5 and Pursuit; and Saturn ION vehicles. This second and final phase will include the Chevrolet Equinox and Uplander, and the Pontiac Montana SV6 and Torrent. Please discard all copies of bulletin 12191.

**Customer Letter Mailing**

The customer letter mailing for this second phase will begin on July 16, 2013.

**Global Connect (GWM)**

The VINs are currently available on the "Investigate Vehicle History" (IVH) screen.

**Campaign Initiation Detail Report (CIDR)**

The CIDR is not available for Special Coverage Adjustments.