



Internal notification for: G_0000164141 09275B - Special Coverage - Fuel
Odor or Spotting on Ground - Replace Fuel Pump Module - Revised
gm_gmmsg_q01 to

04/18/2013 09:14 AM

2 attachments



09275B bulletin.pdf



GM Style Sheet.css

Your email client does not support HTML messages

Date: 04/18/2013

Ref. number: Service / Field Action / G_0000164141

Subject 09275B - Special Coverage - Fuel Odor or Spotting on Ground - Replace Fuel Pump Module -
: Revised

GM CUSTOMER CARE AND AFTERSALES
DCS2942

URGENT - DISTRIBUTE IMMEDIATELY

Date: April 18, 2013

Subject: 09275B - Special Coverage Adjustment
Fuel Odor or Spotting on Ground - Replace Fuel Pump Module

Models: 2006 Chevrolet Cobalt, Pontiac G4, and Saturn ION Originally
Sold or Currently Registered in Alabama, Arkansas, California,
Florida, Georgia, Hawaii, Louisiana, Mississippi, North Carolina,
New Mexico, Oklahoma, South Carolina, Tennessee, and Texas
and
2007 Chevrolet Cobalt, Pontiac G5, and Saturn ION Originally
Sold or Currently Registered in Alabama, Arkansas, Georgia,
Hawaii, Louisiana, Mississippi, North Carolina, New Mexico,
Oklahoma, South Carolina, and Tennessee

To: All GM Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager,
and Warranty Administrator

Special Coverage Bulletin 09275B has been revised to provide coverage of the condition described in the
bulletin regardless of the vehicle's mileage or age. Customers will be notified of this extended coverage.
Please discard all copies of bulletin 09275A.

Customer Letter Mailing

The customer letter mailing will begin on April 25, 2013.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES