



Certified Service

Date: 5/16/2014

Ref. number: Parts / Action - Special Return / G_0000191914

Subject: **Special Return - Steering Wheel Inflatable Restraint Module Coil**

To: Chevrolet, Buick, GMC, and Cadillac Dealers

DESCRIPTION:

Requesting return of Steering Wheel Inflatable Restraint Module Coils GM Part #19184829 and GM Part #19184830 with a date code on the merchandise label **before April 01, 2010 (10182)**. For replacement parts please order the same part number. All GMCCA Distribution Center inventory has been replaced. Good versus discrepant stock on parts can be determined using the attached date code visual aid.

EFFECTIVE DATE:

Immediately through November 14, 2014

ORDER INPUT:

For replacement part order the same part number, GM Part #19184829 and GM Part #19184830.

GENERAL INFORMATION:

Mail, email or fax a separate PC659 Application for each return to your Administrative PDC and indicate:

1. Type of return - check "12"
2. Comments column - "reference GlobalConnect Action Return message number G_0000191914"

Message Attachment(s):

[19184829Photo.pdf](#) Acrobat PDF (37.53KB)

 [PC659.pdf](#) Acrobat PDF (129.1KB)

 [05-16-14 Copy of this message G_0000191914 - Special Return of Steering Wheel Inflatable Restraint Module Coil .pdf](#) Acrobat PDF (15.51KB)

Contact name:

E-Mail: ___

Department: Parts - Customer Care & Aftersales
WHQ

Phone: ?

Intended roles: Parts Manager, Service Manager

Archives: 6/16/2014

Expires: 5/16/2020

Discrepant stock will have date code
before 10182 (2010, July 01)

